

RECOMMENDATIONS FOR IMPROVEMENTS IN THE PRE-SCHOOL

file En-d-2

1. Have arbor between the sleep room and the main building.

Very inconvenient during wet season and jeopardize the health of the children.

2. Have arbor over the pool. If this is done the usefulness are the following:

1. Used for the younger group activities.
2. Used for the wheel toys.
3. Block building.
4. Carpentry
5. Playing house.

REASONS POOL CANNOT BE USED NOW.

1. Too much water used.
2. Bad in terms of sanitation
3. The heat of the sun keeps the children from ^{the pool} using/for play purpose too long.
4. Leakage of pipe now keeps the pool from being dry.

Recommendations:

1. Have woven cocconut palm and vine to grow.
2. Tear down part of the side of pool to allow the tricycle to be driven in, or
3. Ramp may be made over side for entrance.

STORAGE SPACE FOR OUTDOOR EQUIPMENT

Recommendations:

1. Enclose the bottom of the rest room, to store the planks, see-saw, ladders, wagons, etc.
2. Build separate house for storage. (This is more ideal) If the materials are furnished the boys club or parents may be used for labor, under the direction of a qualified carpenter.

STORAGE SPACE NECESSARY FOR INDIVIDUAL LOCKERS FOR CHILDREN.

1. At present, the coats, sweaters, shoes, are left in the back of the bathroom but an individual locker for children is more ideal.

Recommendation: Orange crates may be used.

1. The old sand box near the jungle gym be filled.

a. during rain it gets filled with water. Children fall or become wet.

Filth is bad in terms of sanitation.

2. Floor of ~~sh~~ room sags.

Roof

3. ^{Roof} Leakage is found in the rest room and in the kitchen.

4. A deep sink installed for washing mops, paint bottles, etc.

Recommendations for improving the playground equipment.

1. Have detachable ring and bar.

2. Horizontal bar may be put up.

3. A junior size basket could be put up for youngsters to play basket ball.

4. Help ^{and advice} may be obtained by the Recreational Department of the City and County.